











































Steracie krúžky






Profil	Typ
	W01
	W01-A
	W02
	W02-A
	W02-B
	W03
	W04
	W04-A
	W05
	W05-A
	W05-B
	W07
	W08
	W08-A
	W08-B

Profil	Typ
	W09
	W10
	W11
	W11-A
	W12
	W12-A
	W13
	W17
	W18
	W25
	W26
	W27
	W27-E2
	W27-E5









Piestnicové tesnenie

Profil	Typ
	R01
	R02
	R02-A
	R02-B
	R03
	R04
	R04-B
	R05
	R06
	R07
	R08
	R08-A
	R08-B
	R08-C
	R09-D











Profil	Typ
	R09-DH
	R09-S
	R09-SH
	R09-SHa
	R1011
	R1011-1
	R1011-3
	R1011-A
	R1012
	R16-A
	R16-B
	R17
	R19
	R19-B
	R20

Profil	Typ
	R21
	R24
	R24-A
	R35
	R35-A
















Vodiace krúžky

Profil	Typ
	G01
	G02
	G03
	G04
	G05
	G06
	G07
	G08
















Rotačné tesnenia
















Profil	Typ
	RT01
	RT02
	RT03
	RT04
	RT06
	RT07
	RT08
	RT09
	RT10
	RT19











Ťažké strojárstvo

Profil	Typ
	W01
	W02
	W03
	R02-B
	R03
	R04-B
	R24
	R24-A
	P09
	P09-A
	P09-H
	P23-A
	P23-C
	P23-H
	P23-HA







Piestne tesnenia







Profil	Typ
	P01
	P01-B
	P02
	P02-A
	P03
	P04
	P04-A
	P05
	P06
	P07
	P08-D
	P08-DH
	P08-DP
	P08-S
	P08-SH

Profil	Typ
	P09
	P09-A
	P09-B
	P09-C
	P09-LF
	P1011
	P1011-01
	P1011-03
	P1011-A
	P1012
	P16-A
	P17
	P19
	P20
	P21

Profil	Typ
	P23
	P23-A
	P23-B
	P23-C
	P23-H
	P23-HA
	P23-LF
	P35
	P35-A
	P36

Statické tesnenia

Profil	Typ
	RT13
	RT13-AX
	RT13-AR
	RT14
	RT15
	RT16

Oporné krúžky	
Profil	Typ
	B08
	B09
	B10
	B11
	B12
	B13